

MISSOURI DEPARTMENT OF HEALTH STATE PUBLIC HEALTH LABORATORY DATAMASTER MAINTENANCE REPORT

RECEIVED DHSS Breath Alcohol Program
By Carol Day at 8:15 am, Mar 04, 2010

N. W. C.		
Complete this report in duplicate at the time of the regular is repaired. Send copy to Department of Health; retain original		ce check, and whenever instrument
DATAMASTERSN # 94 11 LCX	m copulation inc.	DATE OF INSPECTION
LOCATION OF INSTRUMENT (STREET AND CITY)		01-15-10 TIME OF INSPECTION
1414 EVERGREEN PERC - WELL		<u>2330</u>
CHECKLIST: Place a check (<) to the left of each item if four in observed values where determined.) Unchecked items must		
DIAGNOSTIC CHECK (PRINTOUT ATTACHED) PASS		
COMPUTER	DETECTOR	
PROGRAM	☐ FILTERS	
HEATERS SAMPLE CHAMBER 49 °C RASS	QUARTZ STANDARD	
☐ FLOW DETECTOR	☐ CALIBRATION	
D PUMP HIGH SPEED	☐ PRINTER	
☐ INDICATOR LIGHTS		
TIME AND DATE		
□ SIMULATOR TEMPERATURE (34 °C ± 0.2°C) 34°C	PASS	
CALIBRATION CHECK - PASS		
Run three tests using a standard solution. All three test		
spread of .005 or less. Check the box corresponding to t RECIBCULATION PUMP)	ne standard solution being use	d. (PHINTOUT ATTACHED) (USE
0.100% STANDARD - MUST READ BETWEEN 0.095% a	ind 0.105% INCLUSIVE	
(ONLY ONE STANDARD - MUST_READ BETWEEN 0.038% a		
TEST 1 - , 695 TEST 2 - , 4		r3 F ,095
PERFORM R.F.I. TEST (PRINTOUT ATTACHED) (ASS		
NUMBER OF REFUSALS, SINCE LAST MAINTENANCE RE	PORT, AND NUMBER OF BRE	ATH TESTS IN EACH RANGE AS
FOLLOWS: (DO NOT INCLUDE SIMULATOR TESTS)	•	
REFUSALS (004) () (.0509)	(.1014) (.1519) Ø (Over .19)
List any new parts and describe any alteration or modification	that was made to restore the	instrument to operate satisfactorily
and within established limits (use other side if necessary) TUSTRUMENT WITHIN D.O. H. GL	かりという	
RESET PRINTER RISSON		
·		
BUTH LABS LOT # .09.270	REF. 10 SOLVERUN	EXF-09-23-10
INSPECTING OFFICER	PRINTYNAME	
► Fort 1/42	PIN J. BRUGMA	INN 662
TYPE II PERMIT MUMBERIEXPIRATION DATE # 920015 02-016-11	(3)4) 553 - 80	010



CERTIFICATE OF ANALYSIS

Certified Alcohol Reference Solution for Simulator

Random Samples of Lot Number 09270 of Alcohol Reference Solution for Simulator were analyzed by gas chromatography and found to contain 0.1207 percent (w/vol) ethyl alcohol. The expiration date for this lot number is September 23, 2010 at 11:59 PM.

When used in a calibrated Simulator, operating at 34°C +/- .2°C, this solution will give a breath alcohol analysis instrument reading of 0.10 percent BAC.

The alcohol and water used in this solution were free of test interfering substances.

Ted L. Pauley, President GUTH LABORATORIES, INC.

Face This Side Down - This Edge In First

BAC DataMasterEvidence Ticket

STRIE OF MISSOURI WELLSTON POLICE DEPORTMENT

990 9978MASTER 1287AL NUMBER 949148 81/15/16

ARREST TIME: 31489

308 PECT MANE:
TEST

DOB: 81484491 SEX: *
STATE/O.L.: MC/TEST

ARRESTING OFFICER:
BRUGMANN
OFFICER I.D.: 668
PERMIT NUMBER: \$20015
EMPIRATION DATE: 82486/11
MISCELLAMEDUT DATE:
AFI TEST

-- PREATH MALYCIS ---

BLANK TEST .000 20:00 INTERNAL STANDARD VERIFIED 20:00 RADIO INTERFERENCE Face This Side Down - This Edge In First

BAC DataMasterEvidence Ticket

STATE OF MICROURY SELLOTOR ACTION DEPARTMENT

DAC DATAMASTER SERIAL MUNISCA 900140 01/15/10

TESTING OFFICER:

BRUCHRYN:
OFFICER 1.2.: 668
PERMIT NUMBER: 928015
EMPIRATION DATE: 92806:11
MISCELLAMEOUS DATE:

--- 3076041308 #006 ---

	BLAW TEST	, 90A	20101
	INTERMEL STAMBARD	A Section of the section of	99×51
	EVTERNAL STANDARD	, j es	29:51
	TREACH THIST	, OGA	23:52
	EXTERMAL STRUBED	,990	23:59
	BLATK TROT		23159
	EXTERNAL STANDARD	.095	23:54
٦	SLOVEY TROY		93135

Operator Signature

2208-02

ator Signature

2208-02

Face This Side Down - This Edge In First

BAC DataMaster Evidence Ticket

STATE OF MISSOURY MELLSTON POLICE DEPARTMENT

RAC DATAMESTER SERIAL NUMBER SABIAB 81/15/19 23:33

-- DIRECTIO CHECK ...

COMPUTER:

MAR

 $\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{n}\sum_{i=1}^{n}\sum_{j=1}^{$

The Care

COMPLE CHAMBER

7.96

FLOW DEVELOTORS

OMAY

OUMF

HISH SPEEDS

NOTE:

PETECTORS

CKM

FILTERS

7546584

OURKIZ STRNIARD:

OKAY

CALIDAGTICAL

的数字字

- PRIMTER TEST

THERE TO KEE - . . TO LECENTED A CARROLLERS HE BOUNDARY TO JOINT SECRET SHE IN THE PROPERTY OF THE SECRET SHE IN THE SECRET SHE SECRET SHE IN THE SECRET SHE IN THE SECRET SHE IN THE SECRET SHE SECRET SHE SECRET SHE SECRET SHE SECRET SHE SECRET SHE SECRET S

Operator Signature

2208-02